# New York State Department of Transportation PIA Safety Flag NB2258W007

By: Alex Abreu

Flag Date: July 27, 2022

Superseding Information:

No Flags Superseded

#### Structure Information

BIN: 1065318 Region: 11 - NEW YORK CITY

Feature Carried: 278I278IX2M23027 County: KINGS

Feature Crossed: 6TH AVENUE Political Unit: City of NEW YORK
Orientation: 8 - NORTHWEST Approximate Year Built: 1962

Posted Load Matches Inventory: Yes

Bridge Load Posting (Tons): Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp Number of Spans: 322

#### **Verbal Notification Information**

Person Notified: Heinz Joachim, P.E. Date: July 27, 2022 7:45:00 AM

Of: NYSDOT Region 11

#### Signature Information

Signature: Alex Abreu, P.E. 099761-1 Date: July 27, 2022

Reviewed By: Robert Kemp Date: July 27, 2022

Attachments: 5

Flag Date: July 27, 2022

## Flagged Elements


# **No Flagged Elements**

## Flagged Condition Description

The pedestrian signal pole located on the sidewalk under Span 198 adjacent to the right end of Pier 197 (intersection of 32nd Street and 3rd Avenue EB) is broken at the base resulting in the signal pole laying on the ground. Due to the broken signal pole, there are exposed wires at the base. The signal pole is partially laying in the street. This area is accessible to pedestrians but is currently coned off with yellow caution tape. This is a newly flagged condition.

Flag Date: July 27, 2022

## Flag Photographs



**Attachment Description: Safety PIA Flag Location** 

Flag Date: July 27, 2022

Photo Number: 2 Photo Filename: 22\_113\_1978.jpg



Attachment Description: General view of the flagged condition under Span 198 adjacent to the right end of Pier 197. Looking Begin and Right.

Photo Number:

Photo Filename: 22\_113\_1980.JPG



Attachment Description: The sidewalk at the right end of Pier 197 under Span 198. The pedestrian signal pole is broken with exposed wires at the base. The area has been coned off with yellow caution tape. Looking Right.

Photo Number:

Photo Filename: 22\_113\_1982.JPG



Attachment Description: The sidewalk at the right end of Pier 197 under Span 198. The broken signal pole is laying on the ground on top of the sidewalk and partially into the street. Looking Right.

PIA Safety Flag NB2258W007

BIN 1065318 Flag Date: July 27, 2022

Photo Number: 5 Photo Filename: 22\_113\_1983.JPG



Attachment Description: The sidewalk at the right end of Pier 197 under Span 198. The broken signal pole has exposed wires at the base which are accessible to pedestrians but the area has been coned off with yellow caution tape. Looking End.